EAST Search History

Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	1147	73/23.31.ccls.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 10:39
L2	1	1 and (exhaust near4 gas\$2) and particles and (electric near4 charge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 10:43
L3	1107	(exhaust near4 gas\$2) and particles and (electric near4 charge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR .	ON	2008/01/20 10:44
L4	. 32	3 and ((vary or varying) near4 charge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 10:47
L5	7	4 and (charge near4 states)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 10:53
L6	7	4 and (charge near4 state)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 11:05
L7		6 and (charge near4 power)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 11:06
L8	103	3 and ((vary or varying or change or changing) near4 charge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 12:18

EAST Search History

L9	24	8 and (charge near4 state)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 12:18
L10	1	9 and (measure near4 charge)	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 13:28
L11	19	US-2950387-\$.DID. OR US-3247375-\$.DID. OR US-3742475-\$.DID. OR US-4456883-\$.DID. OR US-4531486-\$.DID. OR US-4939466-\$.DID. OR US-4959010-\$.DID. OR US-5475311-\$.DID. OR US-20020000810-\$.DID. OR US-20030006778-\$.DID.	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 14:28
L12	4	11 and 3	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON <u>.</u>	2008/01/20 14:28
L13	0	11 and 8	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 14:28
L14	0	13 and 5	US-PGPUB; USPAT; USOCR; EPO; JPO; DERWENT; IBM_TDB	OR	ON	2008/01/20 14:28

1/20/2008 2:36:47 PM Page 2 C:\Documents and Settings\RFrank\My Documents\EAST\Workspaces\MethodandSensorforMeasuringParticleEmmissions10562067.wsp